M989 HEMAT Trailer...

WHAT'S THE SUPPORT SITUATION?



Dear Half-Mast,

We have a tough time getting parts for the M989 HEMAT trailers in our unit. I hear there's a support solution in place. What's the story on this?

SGT D.A.

Dear Sergeant D.A.,

You heard right. The Army has authorized a swap-out of all basic M989 HEMAT trailers, NSN 2330-01-109-4258, for M989A1 HEMATs, NSN 2330-01-275-7474.

Just give your vehicle's serial or registration number to Marleen Fiantaco at TACOM LCMC. She'll give you disposition instructions for the basic M989. The quickest way to get the replacement trailer, NSN 2330-01-275-7474, LIN T45465, is to submit a DA Form 5106, Mission Support Plan (MSP), *through your chain of command.*

Contact Marleen at DSN 786-9362, 586-282-9362. Or email: **marleen.fiantaco@us.army.mil**

Half-Mast



Locate M989 trailer serial or registration number